Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: OTTO 14-23H

Field Name: BAILEY Well File #: 28459

Date Incident:9/28/2014Time Incident:10:40Facility ID Number:County:DUNNTwp:146Rng:94Sec:23Qtr:

Location Description:

Submitted By: Troy Dockter Received By:

Contact Person: Troy Dockter

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 58 Gallons 58 Gallons 58 gallons

Description of Other Released Contaminant:

Involved fluid was Frac fluid.

Inspected: Written Report Received: 3/11/2015 Clean Up Concluded: 9/28/2014

Risk Evaluation:

Initial cleanup occurred immediately following spill. All contaminated material will be removed from location following spill.

Areal Extent:

Potential Environmental Impacts:

Limited till cleanup completed following Frac.

Action Taken or Planned:

Investigation ongoing. Equipment operator was primary causal factor.

Wastes Disposal Location: Clean Harbors, Sawyer, ND

Agencies Involved:

Updates

Date: 9/30/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location fracking fluid tank overflow, remained on location according to the report. NDIC retains oversight.